





M - ISO Metric Coarse Thread DIN 13

Forming Taps Black Ring - TORNADO

DIN 371 HSS-E PM
straight oil grooves
for steel, heat treatable steel
and chemical resistant steel

Group 305
for blind and through holes



Art.-No.		305/4853		
Technology	Page 7.1	PM-Line by Schumacher Black Ring		
Chamfer Length	Page 7.4	C / 2-3 x P		
Surface	Page 7.5	TiCN		
Tolerance	Page 7.6	ISO2X (6HX)		
Material Groups	Page 7.7	1a. general construction steel 1b. high strength steel 2. chemical resistant steel		

Ød ₁	P _{mm}	L ₁	L ₂	d ₂	□	⌀ _{h7}			
M 1	0,25	40	5	2,5	2,1	0,9			
M 1,2	0,25	40	5	2,5	2,1	1,1			
M 1,4	0,3	40	7	2,5	2,1	1,25			
M 1,6	0,35	40	8	2,5	2,1	1,45			
M 1,7	0,35	40	8	2,5	2,1	1,55			
M 1,8	0,35	40	8	2,5	2,1	1,65			
M 2	0,4	45	8	2,8	2,1	1,8			
M 2,2	0,45	45	9	2,8	2,1	2,0			
M 2,3	0,4	45	9	2,8	2,1	2,1			
M 2,5	0,45	50	9	2,8	2,1	2,3			
M 2,6	0,45	50	9	2,8	2,1	2,4			
M 3	0,5	56	10	3,5	2,7	2,75	●		
M 3,5	0,6	56	11	4	3	3,2			
M 4	0,7	63	12	4,5	3,4	3,65	●		
M 5	0,8	70	14	6	4,9	4,6	●		
M 6	1	80	16	6	4,9	5,55	●		
M 7	1	80	16	7	4,9	6,55			
M 8	1,25	90	18	8	6,2	7,4	●		
M 9	1,25	90	18	9	7	8,4			
M 10	1,5	100	20	10	8	9,3	●		
M 12	1,75	110	22	12	9	11,1			





M - ISO Metric Coarse Thread DIN 13

Forming Taps

DIN 371 HSS-E
straight oil grooves
for steel, non-ferrous steel
and heat treatable steel

Group 306
for blind and through holes



Art.-No.		306/53	306/2553	306 B/2553	
Technology	Page 7.1	High Volume by Schumacher	High Volume by Schumacher		
Chamfer Length	Page 7.4		C / 2-3 x P		
Surface	Page 7.5	bright	TiN	TiN	
Tolerance	Page 7.6	ISO2X (6HX)	ISO2X (6HX)	ISO3X (6GX)	
Material Groups	Page 7.7	1a. general construction steel 1b. high strength steel 6. copper alloys			

Ød ₁	P _{mm}	L ₁	L ₂	d ₂	□	⌀ _{h7}			
M 1	0,25	40	5	2,5	2,1	0,9			
M 1,2	0,25	40	5	2,5	2,1	1,1			
M 1,4	0,3	40	7	2,5	2,1	1,25			
M 1,6	0,35	40	8	2,5	2,1	1,45			
M 1,7	0,35	40	8	2,5	2,1	1,55			
M 1,8	0,35	40	8	2,5	2,1	1,65			
M 2	0,4	45	8	2,8	2,1	1,8	●	●	
M 2,2	0,45	45	9	2,8	2,1	2,0			
M 2,3	0,4	45	9	2,8	2,1	2,1			
M 2,5	0,45	50	9	2,8	2,1	2,3	●	●	
M 2,6	0,45	50	9	2,8	2,1	2,4			
M 3	0,5	56	10	3,5	2,7	2,75	●	●	●
M 3,5	0,6	56	11	4	3	3,2			
M 4	0,7	63	12	4,5	3,4	3,65	●	●	●
M 5	0,8	70	14	6	4,9	4,6	●	●	●
M 6	1	80	16	6	4,9	5,55	●	●	●
M 7	1	80	16	7	4,9	6,55			
M 8	1,25	90	18	8	6,2	7,4	●	●	●
M 9	1,25	90	18	9	7	8,4			
M 10	1,5	100	20	10	8	9,3	●	●	●
M 12	1,75	110	22	12	9	11,1			

